

SABS

Certificate of Registration

This is to certify that the Quality Management System of

**WILEC
(A DIVISION OF ACTOM (PTY) LTD)
OLIFANTSFONTEIN**

*has been assessed and found to
satisfy the requirements of*

**ISO 9001:2008
QUALITY MANAGEMENT SYSTEMS - REQUIREMENTS**

in respect of

**THE MANUFACTURING AND SALE OF BRIGHT ANNEALED, ENAMELLED AND
WRAPPED ELECTRICAL COPPER CONDUCTOR USING INSULATING MATERIALS
SUCH AS POLYIMIDE FILM, GLASS, PAPER AND NOMEX**

EXCLUDING CLAUSE:

7.3 DESIGN AND DEVELOPMENT

This certificate, including the schedule which forms an integral part thereof:

- is issued without alteration;
- is identified by the applicable registration number;
- is subject to any condition or limitation contained therein;
- is valid subject to ongoing compliance with certification requirements;
- bears the embossed SABS Commercial seal. In the absence of the seal, the certificate and the schedule shall be invalid; and
- the certificate may be authenticated by referring to the register of "Certified Clients" on the SABS Commercial website (www.sabs.co.za)

Registration Number **LS 131**

Effective Date **12 March 2016**

Expiry Date **15 September 2018**

Date of Original Registration **17 February 1988**

Chief Executive Officer



SABS
COMMERCIAL

SABS COMMERCIAL SOC Ltd.
1 Dr Lategan Rd, Groenkloof, Pretoria
Republic of South Africa

AA1M0005535

SCHEDULE TO CERTIFICATE OF REGISTRATION

1. REGISTERED ORGANIZATION	
1.1 Name	Actom (Pty) Ltd
1.2 Name under which business is conducted	Wilec
1.3 Registration or identity number	2008/001863/07
2. ADDRESS(ES) OF REGISTERED ORGANIZATION	28 Main Road, Clayville Extension 4, OLIFANTSFONTEIN
3. SCOPE OF REGISTRATION	The manufacturing and sale of bright annealed, enamelled and wrapped electrical copper conductor using insulating materials such as polyimide film, glass, paper and nomex Excluding clause: 7.3 Design and development
4. SIC CODES, EA & CATEGORIES	
4.1 SIC CODE(S)	36300
4.2 EA CODE(S)	19
5. COMMODITIES MANUFACTURED BY REGISTERED ORGANIZATION UNDER SABS CERTIFICATION MARK SCHEME	SANS 60317-8 / SABS IEC 60317-8 Specifications for particular types of winding wires Part 8: Polyesterimide enamelled round copper wire, class 180 SANS 60317-4 / SABS IEC 60317-4 Specifications for particular types of winding wires Part 4: Solderable polyurethane enamelled round copper wires, class 130 SANS 60317-13 / SABS IEC 60317-13 Specifications for particular types of winding wires Part 13: Polyester or polyesterimide overcoated with polyamide-imide enamelled round copper wire, class 200 SANS 60317-0-1 / SABS IEC 60317-0-1 Specifications for particular types of winding wires Part 0-1: General requirements - Enamelled round copper wire

SCHEDULE TO CERTIFICATE OF REGISTRATION**RECORD OF AMENDMENTS TO REGISTRATION CERTIFICATE**

Original date of issue : 1988-02-17

Amendments

1989-04-20	Revised Code of Practice SABS 0157-1987
1991-11-15	Code of Practice renumbered SABS ISO 9000 in accordance with international use, with various parts thereof identified by the relevant subnumbers in the ISO 9000 series
1996-02-19	a) Certificate of Listing reissued as Certificate of Registration, reflecting new registration scheme and new SABS logos and also the RvA (RvC) logo and scope sector b) Standard Industrial Classification (SIC) number added c) Amended conditions for registration
2000-08-03	Certificate of Registration with triennial expiry date
2003-10-31	Regraded to SABS ISO 9001:2000
2005-11-11	a) Company registration number changed from 1982/06563/07 to 2004/036123/07 b) Name changed from Transwire (Pty) Ltd to Savicio Holdings (Pty) Ltd
2007-02-28	Certificate of registration reissued with triennial expiry date
2010-02-03	a) Re-certification audit b) Conversion of ISO 9001:2000 to ISO 9001:2008
2013-02-06	a) Re-certification audit b) Change of company holding name from Savico Holdings (Pty) Ltd to Actom (Pty) Ltd c) Change of company registration number from 2004/036123/07 to 2008/001863/07
2014-12-10	Change of trading name from Transwire to Wilec
2016-03-12	a) Re-certification audit b) Certificate re-issued without RvA logo